



Worldwide repairs carried out with PolymerMetal®

REP-# 014



Corrosion damages at a brake drum caused by brake dust were repaired by using MM-metal SS-steelceramic and Hardener yellow.

MultiMetal
the MetalExistenceCompany®