



*Worldwide repairs carried out with PolymerMetal®*

**REP-# 089**



Repair of the soot blower compressor at a heat station by coating the additional cooler with Ceramium. The coating was affected in two steps: a first application of Ceramium pasty type, afterwards a second application with Ceramium liquid type.

**MultiMetall**  
the MetalExistenceCompany®